Classification and Evaluation Methods of Modern Urban Industrial Heritage Landscape:
# A Case Study of Shaanxi Province, China

September 2020

Weiyu Lian

Nowadays, as many countries are facing the transformation of industrial format, a large number of factories ceased production and became abandoned. The protection of industrial heritage has become a problem. The question related to what to do with it is highly relevant to today's urban transformation. Thus, knowing the characteristics of industrial heritage can help in better implementation of conservation and new development. My study will explore the most effective way to classify and evaluate the industrial heritage landscape, and will attempt to provide a new, comprehensive guideline for the classification, evaluation and presentations of industrial heritage landscape.

Supervisors

Prof. Branka Dimitrijevic
Dr. David Grierson

Before

Heat treatment workshop

Production of slender steel wire

Office

Oil tempering furnace workshop

Pickling workshop

Machine repair

Exquisite wire grinder workshop

Packaging workshop

Finished goods store

Wire drawing workshop

New equipment workshop

Office

After

North Street of Factory

Left &Right Alley

Grandmaster Alley

11#   10#   09#

Memory Street

Factory Esat Street

01#

02#

Roof plaza

12#   Art Street

Sunken plaza

03#

Literature Street

08#

East Street of Factory

04#   05#

07#

Creative Street

06#   06#   Water

Management Centre

Factory South Street

Main entrance

Location

China

South Korea

Xi'an City
Shaanxi Province
China

East China Sea

Sea

Changes in Shaanxi Steel Factory from 1965 to now
Located in Xi'an City, Shaanxi Province, China